



Inspection Report

CLAWS N PAWS WILD ANIMAL PARK INC

Customer ID: **2246**

Certificate: **23-C-0013**

Site: 001

CLAWS N PAWS WILD ANIMAL PARK INC

1475 LEDGEDALE RD

Type: ROUTINE INSPECTION

LAKE ARIEL, PA 18436

Date: May-17-2012

3.125 (a) REPEAT

FACILITIES, GENERAL.

Section 3.125(a) Structural strength: The animal housing facilities shall be structurally sound and shall be maintained in good repair to protect the animals from injury and to contain the animals.

1) The enclosure housing the two lions has a small gap under the fence to the left of the viewing window. The gap needs to be closed.

2) The enclosure housing the bison has a board pulled up and away from the bottom of the fence in the front section of the enclosure (by the camel) creating a gap. The adjacent section of fence has wire strands protruding out from the board at the bottom. The fence needs to be repaired.

The facility needs to ensure its maintenance program keeps the animal enclosures in good repair to protect the animals from injury and to contain the animals.

An exit briefing was conducted with Mary Geib, VMO; David Oelberg, VMO; and the licensee.

Prepared By:

MARY E GEIB, D V M USDA, APHIS, Animal Care

Date:

Title: VETERINARY MEDICAL OFFICER Inspector 1021

May-17-2012

Received By:



(b)(6), (b)(7)(c)

Date:

Title:

May-17-2012