MIGELE 250121407500044 insp id



Inspection Report

CLAWS N PAWS WILD ANIMAL PARK INC

Customer ID: 2246

Certificate: 23-C-0013

Site: 001

CLAWS N PAWS WILD ANIMAL PARK INC.

1475 LEDGEDALE RD

Type: ROUTINE INSPECTION

Date: Sep-06-2012

LAKE ARIEL, PA 18436

3.125 (a)

FACILITIES, GENERAL.

Section 3.125(a) Structural strength: The animal housing facilities shall be structurally sound and shall be maintained in good repair to protect the animals from injury and to contain the animals.

The wall inside the shelter for the four African crested porcupines has a jagged rough area where the metal liner has been bent up just above the floor. The wall with the metal lining must be repaired to protect the animals from injury. The wood floor of the shelter has several holes outside the enclosure in the service area. The floor must be repaired to be structurally sound and to deter the entrance of rodent pests.

The facility must ensure its maintenance program keeps the animal enclosures and buildings in good repair to protect the animals from injury and to contain the animals.

Correct by September 20, 2012.

An exit briefing was conducted with the licensee.

Prepared By:

Title:

MARY E GEIB, D V M

USDA, APHIS, Animal Care

VETERINARY MEDICAL OFFICER Inspector 1021

Sep-06-2012

Received By:

(b)(6),(b)(7)(c)

Date:

Date:

Title:

Sep-06-2012

Page 1 of 1